



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Rusty Netz	Environmental Coordinator
OSM	Henry Austin	
OGM	Karl Houskeeper	Environmental Scientist III

Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE OVERSITE
Inspection Date:	Wednesday, December 06, 2006
Start Date/Time:	12/6/2006 8:30:00 AM
End Date/Time:	12/6/2006 12:00:00 PM
Last Inspection:	Tuesday, November 14, 2006

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 20 Deg. F.

InspectionID Report Number: 1152

Accepted by: pgrubaug

12/20/2006

Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**

Operator: **SUNNYSIDE COGENERATION ASSOCIATES**

Site: **STAR POINT REFUSE**

Address: **ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

152.81	Total Permitted
88.78	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☐ Underground
☐ Surface
☐ Loadout
☐ Processing
☒ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending actions: Task ID #2620 Midterm Permit Review.

Inspector's Signature: _____

Karl Houskeeper

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Date Wednesday, December 06, 2006

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0070042
 Inspection Type: COMPLETE OVERSITE
 Inspection Date: Wednesday, December 06, 2006

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

Pending actions: Task ID #2620 Midterm Permit Review.

The following permits were reviewed:

- Mining permit C/007/042 issued November 14, 2003 and expires November 14, 2008.
- UPDES permit #UTG040025 effective May 1, 2003 and expires midnight April 30, 2008 (under general permit UTG040000).
- Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.
- SPCC plan is not required.
- Certificate of Insurance effective 08/01/2006 and terminates 08/01/2007.
- Reclamation agreement is dated October 14, 2003 and signed by both parties.
- Storm Water Permit UTR000604, effective 08/29/02 and expires @ midnight 12/31/06 (under general permit UTR000000).

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected on September 19, 2006 and are included in a report dated October 11, 2006. The report was P.E. certified, dated, and stamped. No problems were noted.

4.e Hydrologic Balance: Effluent Limitations

The October 2006 discharge monitoring reports were reviewed. No discharge occurred from any of the outfalls.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on September 19, 2006 and was included in a report dated October 11, 2006. The report was P.E. dated, stamped, and signed by a registered P.E. in the State of Utah.

20. Air Quality Permit

The air quality permit DAQE-239-02 was issued on April 1, 2002 and remains in effect.

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,254,000.